

Old and ineffective heat exchangers can prove to be maintenance and energy usage liabilities, costing plants tens of thousands of dollars annually. Anguil's crews are constantly in the field replacing and supplementing existing heat recovery systems, helping meet energy efficiency and compliance goals. A few recent examples include:

- Anguil replaced the heat exchanger in a competitive thermal oxidizer, raising destruction efficiency from 92% to +99%, bringing the customer into compliance with regulatory standards.
- In three separate applications the addition of Anguil secondary heat exchangers dramatically lowered plant-operating costs.
- A poorly designed competitor's heat exchanger, plugged by silicone, was replaced with a state-of-the-art Anguil heat exchanger.
- A chemical plant replaced their corroded heat exchanger with an Anguil design.
- The heat exchanger in a competitor's oxidizer, destroyed by HCL, was replaced by Anguil.



For more information on these applications or your specific needs contact Anguil's Aftermarket team at (414) 365-6400.